Certificate of Location of Government Corner

ID#:511904 **Description:** 1/4 SEC COR 19 30 51 **Date Set:** 12/17/1987 **County:** Olmsted

Section: 19 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

Corner is at the surface
County Survey Disk in gate post ENE 4.09'
County Survey Disk in CP WNW 11.56'
County Survey Disk in 24" Burr Oak SE 58.52'
Sign on fence post
This corner is located by GPS measurement

Corner History:

Gov't notes: set 1/4-sec-post, 40 chs. Dug trench. 5" Burr Oak, S83-1/2ºE 58 lks

11-1894 W.Fraser pg 559 no 514 sec 30 found remains of old stake and stump of BT with marks plain proving that stake is correct. Drove new stake with stone on each side of stake. 1/16 W - drove iron & wood stakes

11-25-1987 County Surveyor found charred wood remains beneath drag tooth, did not find stones on each side of stake (W.Fraser).

12-9-1987 County Surveyor found W.Fraser's 1/16 W of 1/4-corner: 1-1/4"x10" with flatened top.

12-10-1987 County Surveyor found 2 limestones 6" deep, about 1' apart.

12-17-1987 County Surveyor set cast iron cap on telspar pipe at point between 2 stones.

3-24-2011 County survey crew found CIC on telspar pipe in good condition.