Certificate of Location of Government Corner

ID#:511905 **Description:** W SEC COR 19 30 51 **Date Set:** 11/7/2005 **County:** Olmsted

Section: 19 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' SW of CP for fences E-W-N
County Survey Disk in NE side 18" Oak NW 25.43'
Sign on CP 1' NE
This corner is located by GPS reference stations "Gator A & B"

Corner History:

Gov't notes (9/1853): set post for corner. 10" Burr Oak, S62ºW, 42 lks. 10" Aspen, N4ºW, 105 lks. 10" Burr Oak, N17ºE, 103 lks.

4-1875 T. Hunter pg 336 no 330 found old stake in ground and print indicated by NW & SWBT. Set new stake. 1/16 W - set stake 1/16 S - set stake 1/16 center NE 1/4 sec 25 - set stake

11-1894 W.Fraser pg 559 no 514 corner fence post avered by Mr. Cully as placed in place of original stake by himself tested on remaining BT. 1/16 S - found stake 1/16 E - drove iron & wood stakes on line

6-19-1973 County Surveyor ran part of extensive survey to corner area. Found limestone 3x7x12" in good vertical position just South of corner post.

2-28-2005 County Surveyor found stone in good condition up 0.2'. Stone falls south of corner post for fence E-W & north.

11-17-2005 County Surveyor removed triangle shaped stone. Set 3' telspar w/CIC up 0.2' from angle turned to stone in February. CSD with concrete nail in NE side of 18" Oak now 25.43'. Set sign on corner post.