Certificate of Location of Government Corner

ID#:511906 **Description:** W 1/4 SEC COR 19 51 **Date Set:** 12/18/1987 **County:** Olmsted

Section: 19 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 6 1/2' south 29" Red Oak used as CP
Sign on S side 29" Red Oak 4' north
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes. John Ball Deputy Surveyor: North between sections 19 and 24 40.00 chs. Set post for quarter section corner, built mound with trench at center drove charred stake planted osage orange S.E. and apple seeds N.E.

4-1878 Thomas Hunter County Surveyor (p. 336 No. 330). At west 1/4-corner 19 Elmira found remains of old stake by fence corner of fences running east, west and south. Measured west to center stake set at intersecting lines 39.95 chains N 89-1/2° E. and west to 1/4-cor 23, 24 39.67 chains N. 89-1/2° E.

1-1891 Thomas Fraser County Surveyor (Book 7 page 82) surveyed NE-1/4 of section Orion. At east 1/4-corner 24 Orion found stake marked, bearing tree S 75° W. 33 links 18" elm.

12-17-1987 County Surveyor dug for stake to cover line from west corner 23.24 orion over center 24 stake found. Found stake mark with 7" diameter dark spot on south side.

12-18-1987 County Surveyor set telspar pipe with a cast iron cap at stake mark location, which nearly fits 1/4-line from west and line of fence north.

2-28-2005 County Surveyor found CIC on telspar pipe in good condition down 0.2'. Box Elder gone and Red Oak dying. Sign nailed in south side of Oak.