Certificate of Location of Government Corner

ID#:512006 **Description:** 1/4 SEC COR 19 20 51 **Date Set:** 12/18/1987 **County:** Olmsted

Section: 20 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in line with fence east and 1 1/2' west of N-S fence
Face of 3" angle iron CP E 1.38'
County Survey Disk in transmission pole NNW 48.34'
Post w/sign 1' east
This corner is located by GPS measurement

Corner History:

Gov't notes: set 1/4-sec-post, 40 chs, 6" Burr Oak S28-1/2ºW 125 lks

12-11-1987 County Surveyor found nothing. The corner post to fence N-S-E may have destroyed corner.

12-18-1987 County Surveyor set cast iron cap on telspar pipe on N-S-section line, in line of fence E.

2-22-2007 County Surveyor found CIC on telspar pipe up 0.2' in good condition. Set post w/sign 1' east. All ties there did not check.