Certificate of Location of Government Corner

ID#:512204 **Description:** 1/4 SEC COR 22 27 51 **Date Set:** 6/5/2007 **County:** Olmsted

Section: 22 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in line with main line of fence north and old road bed west
This corner is located by GPS measurement

Corner History:

Gov't notes: set 1/4-post and stone 18x14x2", mound & pits.

6-1872 T. Hunter pg 208 no 216 sec 27 found small stake by side of fence post, which was avered to be set in center mound 16 years before. Pits still quite plain. 1/16 E - set stake

6-1873 T. Hunter pg 230 no 233 sec 22-23 found short stake by fence post pg 208 1/16 E - set stake 1/16 N - set stake

7-10-1985 County Surveyor found post hole with limestone pieces packed around. Also found a post stub.

9-1-1989 County Surveyor set up T.N. from 1985 also post mark found 1985 to check position of 1/4-sec-cor to be set. Set 4' long telspar pipe / CIC .

6-5-2007 County Surveyor found telspar pipe w/CIC down 1.0' twisted and bent, took local ties and removed. Set 6' telspar w/CIC in existing hole below bend down 1.3'.