Certificate of Location of Government Corner

ID#:512306 **Description:** 1/4 SEC COR 22 23 51 **Date Set:** 12/6/2004 **County:** Olmsted

Section: 23 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 325' ± west of line of pasture fence south
This corner is located by GPS reference stations "Ask C & D"

Corner History:

Gov't notes: Set post & stone 23x8x3" , mound & pits.

6-1873 Hunter pg 230 no 233 sec 22-23 corner gone for years. Run direct line, set stake M&L 40.05-1/4 chs. 1/16 N - set temporary stake 1/16 S - set temporary stake 1/16 W - set stake 1/16 E - set stone 5x10x16"

4-1878 T.Hunter Bk 5 pg 56 sec 22

7-11-1976 County Surveyor found 2.5x9x18" limestone on SE side of corner post to fence N-S-E-W. Possible corner stone.

7-12-1976 County Surveyor dug but found nothing.

7-25-1985 1/16 E - County Surveyor dug and found stone 5x10x16" as described by Hunter. Set a 0.5"-rod by the stone and pieces of limestone around bottom.

9-1-1989 County Surveyor dug to cover full 1873-Hunter-measure of 1/16 E&W and center sec 22 C.P. and 1/4-sec-corner 21, 22 (CIM). Found nothing.

8-22-1997 County Surveyor needed Center 22 for survey in NW1/4 by GGG so set corner on line from W1/4 Cor. 22 over stone found at 1/6E of Cen. 22 for N-S. E-W to be finalized later.

12-6-2004 County Surveyor set 5' telspar pipe w/cast iron cap down 1.1' from GPS and traverse data in edge of field between owners.