Certificate of Location of Government Corner

ID#:512505 **Description:** SEC COR 25 26 35 36 51 **Date Set:** 7/23/1991 **County:** Olmsted

Section: 25 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' west of CP to fences north and east and 23 1/2' east of centerline of driveway north
County Survey Disk in 24" Burr Oak S 4.41'
County Survey Disk in S side CP E 1.01'
This corner is located by GPS reference stations "Stokes A & B"

Corner History:

Gov't notes: Set post and limerock, 20x10x2", mound & pits. Corner area on high level area with road at corner area and ravines running easterly and northwesterly with roads following ravines.

5-1878 T. Hunter surveyed sec 25, see Bk 5 pg 61

7-6-1989 County Surveyor dug but found no post or stone.

7-23-1991 County Surveyor set cast iron cap on telspar pipe at fence corner which matches T.Hunter's 1878 location. All lines & measures E-S-W-N closely agree with this location.

6-2-2004 County Surveyor found cast iron cap on telspar pipe up 0.5' in good condition.