Certificate of Location of Government Corner

ID#:512506 **Description:** 1/4 SEC COR 25 26 51 **Date Set:** 7/23/1991 **County:** Olmsted

Section: 25 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 2' east of centerline of N-S twp road and 14 1/2' south of centerline of driveway west
County Survey Disk in PP #2745 NW 60.77'
This corner is located by GPS measurement

Corner History:

Gov't notes: Set post and deposited limerock (no size), mound & pits.(Aerial topo map shows corner area in westerly end of rather sharp ravine running east.)

5-1878 T.Hunter Bk 5 pg 61 sec 25 apparently used corner.

8-10-1989 County Surveyor dug and found a post stub.

7-23-1991 County Surveyor set CIC / telspar pipe at location of post stub found 8-10-1989. Set pipe because tele cable would interfere with CIM.

4-11-2000 County Surveyor found CIC/Telspar pipe down 0.6' in N-S twp road in good condition.