Certificate of Location of Government Corner

ID#:512604 **Description:** 1/4 SEC COR 26 35 51 **Date Set:** 6/30/1989 **County:** Olmsted

Section: 26 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is down 0.1'
The corner falls 2' south of fence west and 1' west of fence south
County Survey Disk in CP NNE 2.43'
County Survey Disk in 16" Elm S 16.48'
Sign on CP 2' NNE
This corner is located by GPS reference stations

Corner History:

Gov't notes: Set post and limerock 18x12x2", mound and pits. (Corner of 3 farms. Common land on East side. Gov't notes say land at corner level. Contours drop sharply to south into bottom lands.)

5-12-1989 County Surveyor visited approx. corner location of fences N-S-W, rocky area.

6-27-1989 County Surveyor dug and found a stone 2x12x18" which matches Gov't stone size, stone was leaning north. The stone was set with point down.

6-30-1989 County Surveyor set cast iron cap on square pipe at stone location with stone dug in 0.5' South.

8-11-2011 County survey crew found cast iron cap on square telspar pipe in good condition.