Certificate of Location of Government Corner

ID#:512806 **Description:** 1/4 SEC COR 28 29 51 **Date Set:** 6/6/1996 **County:** Olmsted

Section: 28 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in line with fence north and 10' south of fence east
Post w/sign 2' north
This corner is located by GPS measurement

Corner History:

Gov't notes: Set 1/4-post and stone 6x7x2", mound & pits. [Corner in level flat bottom lands. No road. Corner of 3 farms. Common land on E side.]

6-1857 T. Hunter pg 33 no 52 used corner. Measure west 39.60 chs to center.

6-1878 T. Hunter pg 337 no 331 found original stake standing by side corner fence post. 1/16 N - set stake

6-4-1996 County Surveyor dug at corner post of fence N-S-W but found nothing.

6-6-1996 County Surveyor set cast iron cap on telspar pipe as 1/4-sec-corner midway between section corners N & S and in line of N-S-fences.

2-10-2005 County Surveyor found telspar pipe w/CIC in good condition up 0.4'. Old corner post destroyed. Monument falls inline with fence north and 10' south of fence east, fence to the west being grubbed out by farmer. Set sign and post 2.0' north.

4-30-2007 County Surveyor found telspar pipe w/CIC up 0.3' in good condition.