Certificate of Location of Government Corner

ID#:513406 **Description:** 1/4 SEC COR 33 34 51 **Date Set:** 8/29/1985 **County:** Olmsted

Section: 34 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is at the surface
County Survey Disk in W side PP #2351 (up 7') S 88.48'
County Survey Disk in N side 36" twin White Oak ESE 53.72'
Post w/sign 1' north
The monument is 1.5' W of N-S fence
This corner is located by GPS measurement

Corner History:

Gov't notes: Set 1/4-sec-post M&L, 40 chs. 10" White Oak N46ºE 196 lks. 14" Black Oak N32ºE 184 lks.

4-1878 T.Hunter Bk 5 pg 60 sec 33 found original 1/4-post, standing also the witness trees. Tested it and found correct. 1/16 W - set stone 21x8x3"

7-1-1985 1/16 West of 1/4 Cor. 33-34; County Surveyor dug from a point at T. Hunter's measure from the N-S fence at 1/4 cor. 32-33 to the point shot at 1/4 Cor. 33-34. First clay found a limestone 2"x4"x13"x22" lying flat with wood pieces around the bottom but not dug in at all. Also found pothole with wood piece still in it. Crockery broken around it and piece of limestone 31/2"x41/2"x12" lying down by it. Found another part stub 6' no. of this.

7-2-1985 County Surveyor dug and found nothing.

8-29-1985 County Surveyor set cast iron cap on telspar pipe as corner under the N-S-fence and at double distance from sec-cor-27-28-33-34 (set this survey) over the E-W fence at the 1/16 S (set by Hunter). Set survey marker sign & post 1.0' N.

2-22-2011 County survey crew found cast iron cap on telspar pipe in good condition.