Certificate of Location of Government Corner

ID#:520104 **Description:** 1/4 SEC COR 1 12 52 **Date Set:** 9/7/1988 **County:** Olmsted

Section: 01 **Township:** 105N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is up 0.3'
The corner falls 24' south of fence east and 13' west of N-S fence
County Survey Disk in 8" Butternut SW 7.01'
County Survey Disk in 18" White Oak NNE 26.87'
This monument is located by GPS reference stations.

Corner History:

9-1853 Gov't Notes West on true line between section 1 & 12 Var 10ºE 40.10 Set qr. Section post Br. Oak 6" S84ºE 58 Lks. W, Oak 8 N89ºW 49 80 - 20 To section corner. 4-18-56 Hunter P13 No. 20 S1 used corner. 1/16 W referenced. 1/16 N referenced. 1/16 Center SW 1/4. 1/16 Center SE 1/4 of Sec. 1 referenced.

2-18-1967 Horton P83 No. 123 of Sec. 12. 1/16 E & W. 1/16 S. 1/16 Center NW 1/4 12. 1/16 Center NE 1/14 12.

8-2-1988 County Surveyor dug but found nothing.

8-10-1988 County Surveyor dug but found nothing.

9-7-1988 County Surveyor dug but found nothing. Set CIC/square pipe M&L, This corner matches H. Horton position and seems to best fit T. Hunters measurements of 1856.

8-2-2011 County survey crew found cast iron cap in good condition