Certificate of Location of Government Corner

ID#:520106 **Description:** 1/4 SEC COR 1 2 52 **Date Set:** 8/18/1988 **County:** Olmsted

Section: 01 **Township:** 105N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is up 2'
The corner falls in line with fences east and west
Bottle cap in gate post E 15.59'
Spike in tree NW 21'
Traverse iron ESE 30.29'
Sign nailed to corner post, East, 2'
This corner is located by GPS measurement

Corner History:

10-6-1853 Gov't Notes South 8' W on truel line between Sec. 1 & 2 40.19 Set gr. Sec. Post Br. Oak 8" N3 W 460lks. Br. Oak 7" S5E 603lks. 80.19 chs. Between sec. Corner.

4-1856 T. Hunter P13 No. 20 Sec. 1 used corner. 1/16 East 1/16 Center SW 1/4.

8-1-1988 County Surveyor dug and found old post. Found larger post mark.

8-3-1988 County Surveyor found another post hole going deep in existing fence line 8' west of the one found 8-1-1988.

8-18-1988 County Surveyor set C.I.C./sq. pipe at location of large post hole found 8-1-1988 in E-W fence, matches T. Hunter's survey. Set post and sign 0.7' South of corner.

8-2-2011 County survey crew found cast iron cap in good condition.