Certificate of Location of Government Corner

ID#:520205 **Description:** SEC COR 2 3 10 11 52 **Date Set:** 7/20/2000 **County:** Olmsted

Section: 02 **Township:** 105N **Range:** 12W **Monument Description:** 5/8" copper plug w/punch mark

Reference Ties:

The corner falls 3' west of centerline of CSAH 7 and in line with fence east
Punch cross in S end CMP SE 46.62'
RR spike on post 59.45'
Punch cross in N end CMP NE 51.47'
Pop cap in NE side PP #16987 NW 57.05'
Ref pipe SW 200.51'
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes: William A. Jones, Deputy Surveyor, set a corner post 80.00 chains north of Sec. Cor. 10-11-14-15 and took bearing trees.

10-1923 County Highway Department (B. 41 P. 17) found stone, claimed set by farmers, in center of road. Set hub riser.

10-8-1971 County Surveyor found 2"x12" topped limestone 5' deep and 3.5' west of present center line of road. Set temporary corner since road will be regraded.

11-21-1974 County Surveyor set 1 1/4" pipe as corner. (From 1971 Rps.)

5-16-1997 County Surveyor found 1 1/4" pipe in good condition 3' W centerline CR #7

5-29-1997 County Surveyor set ref pipe.

6-25-1999 County Surveyor tied out corner.

7-2-2000 County Surveyor set 5/8" copper plug w/punch mark at surface from 1999 tie out.

1-10-2008 County Surveyor found 5/8" copper plug w/punch mark at surface in good condition.