Certificate of Location of Government Corner

ID#:520404 **Description:** 1/4 SEC COR 4 9 52 **Date Set:** 12/7/1998 **County:** Olmsted

Section: 04 **Township:** 105N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

Post w/sign 2' north
Fiberglass post beside monument

Corner History:

10-6-1853 Gov't Notes West on true line between sections 4&9 Var 9°48' E 39.98 Set qr. Section post 79.87' to section corner

12-7-1998 County Surveyor dug in old N-S fence line on line between section corners, very poor soil conditions (found nothing). Set Cast Iron Cap on telspar pipe on the E-W section line on East edge of N-S fence line.

11-12-2009 V. Fangman found pipe w/cap leaning badly with cap partially broken by farm machinery. They found that the straight part matched the HARN location from County Surveyor.

11-12-2009 V. Fangman cut off bent part of pipe and set cap on remaining 4 feet of pipe.