Certificate of Location of Government Corner

ID#:520706 **Description:** W 1/4 SEC COR 7 52 **Date Set:** 4/26/1977 **County:** Olmsted

Section: 07 **Township:** 105N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is down 0.1'
The corner falls 86' north of CP to fences north & southeasterly
County Survey Disk in W side gate post S 70.80'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes John Ball, Deputy Surveyor North between 7 and 12. 40.00 chs. Set quarter post. White Oak 20 in. N88ºE 22 lks. White Oak 19 in. N60ºW 40 lks.

11-1877 Thomas Hunter (P. 325 No. 319), County Surveyor, states that the corner was gone but the N.E. bearing tree and the indentation of the grubbed out N.W. bearing tree was plain. Reset the 1/4 post by the Gov't Notes. Set the Center 7 and the E. 1/4 Cor. 7.

4-26-1977 County Surveyor dug on line from the E. 1/4 Cor. 7 over the Center 7 and under the N-S fence, but did not find anything. Set a Cast Iron Cap on a square pipe as the corner at this location.

8-1-2011 County survey crew found cast iron cap on square telspar pipe in good condition