Certificate of Location of Government Corner

ID#:520904 **Description:** 1/4 SEC COR 9 16 52 **Date Set:** 4/21/1980 **County:** Olmsted

Section: 09 **Township:** 105N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1 1/2' south of E-W fence and 9' west of fence north
County Survey Disk in 20" Bur Oak NE 22.15'
County Survey Disk in 10" Bur Oak NE 41.50'
Center of brace post NW 2.4'
Center of CP ENE 9.2'
Post w/sign 1 1/2' north

Corner History:

9-1853 Gov't Notes William A. Jones, Deputy Surveyor West on true line between sections 9 and 16. 40.05' chs. Set quarter section post. Bur Oak 6 in. S76ºW 476 lks. Bur Oak 15 in. N81ºE 181 lks. 80.10 chs. To section corner. Found no further survey records of this corner.

4-21-1980 County Surveyor set a 2' long square pipe with a Cast Iron Cap as the corner. The 1/4 corner is set N-S at 2.97' North of a straight line between the section corners. This location seemed to fit the E-W fence between Sections 9 and 16 better than an on line point which was considered. It fit an average of the line from the N.E. Cor. 16 over the corner post at the 1/16 West and the line from the N.W. Cor. 16 over the corner post at the 1/16 East. The corner is set E-W midway between the section corners. This location holds the fence at the 1/16 West midway to the N.W. Cor. 16 and also fits the projection of the line of the fence at the N. 1/4 Cor. 9 over the fence corner at the 1/16 North of 1/4 Cor. 9-16. Dug for the corner but did not find anything. The monument is 11/2' South of the E-W fence and 9' West of the fence North.

12-8-1998 County Surveyor found Cast Iron Cap on telspar pipe in good condition.