Certificate of Location of Government Corner

ID#:521006 **Description:** 1/4 SEC COR 9 10 52 **Date Set:** 4/30/1980 **County:** Olmsted

Section: 10 **Township:** 105N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 7' east of N-S fence
County Survey Disk in 30" Bur Oak stump ENE 116.6'
County Survey Disk in NE side 22" Blazed Burr Oak SW 18.05'
Steel T post NNW 1/2'
This corner is located by GPS reference stations "Friedrich I & II"

Corner History:

9-1853 Gov't Notes William A. Jones, Deputy Surveyor North between sections 9 and 10. 40.00 chs. Set quarter section post. Bur Oak 6 in. S77ºW 120 lks. Bur Oak 8 in. N321/2º 20 lks. 43.20 chs. Brook 5 lks. Wide runs East.

4-30-1980 County Surveyor dug for the corner. Found a 4" diameter dark spot running down 6" to 8" into yellow soil. This spot came on the line from the W. 1/4 Cor. 9 over the fence corner at the 1/16 East of the Center 9 and on line from the N.E. Cor. 9 over the fence corner at the 1/16 South and very near double this distance. This mark also lines with the slight hump in the ground of the remains of an old fence line running East. Accepted the dark spot as the corner location and set a 2' long square pipe with a Cast Iron Cap as the corner.

12-9-1998 County Surveyor found Cast Iron Cap on telspar pipe in good condition.

12-14-2007 County Surveyor found CIC on telspar pipe up 0.2' in good condition.