Certificate of Location of Government Corner

ID#:521106 **Description:** 1/4 SEC COR 10 11 52 **Date Set:** 7/21/2000 **County:** Olmsted

Section: 11 **Township:** 105N **Range:** 12W **Monument Description:** 5/8" copper plug w/punch mark

Reference Ties:

The corner falls 1.3' west of centerline of CSAH 7 and in line with fences east and west
Bottle cap in E side PP #16974 NW 115.43'
Concrete nail in S side large cresoted CP E 51.74'
Ref pipe NE 64.72'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes North between sections 10 and 11. 40.00 Set quarter section post. Made trench and planted Hawthorne seeds N.E.S.&W. Burr Oak 8 in. N3ºE 1048 lks.

5-1887 Thomas Hunter (P. 311 No. 305), County Surveyor, states road washed out and corner gone. A Mr. Burke avers he set fence running west exactly in line of original corner and corner post 2 rods from original corner. Set stone 4"x5"24" at this point.

10-1923 County Highway Department (B. 41 P. 17) set hub in center of road.

10-8-1971 County Surveyor dug with cat and found 4"x5"x24" limestone 6' deep. Set temporary nail over corner since road will be graded.

6-10-1974 County Surveyor set a 3/4" pipe with a reinforcing rod inside as the final corner flush with the new concrete 1.54' west of centerline CR 7.

5-23-1997 county highway department found pipe in good condition 1.8' west of centerline of CR 7.

6-25-1999 County Surveyor set reference pipe and took ties to corner.

7-21-2000 County Surveyor set 5/8" copper plug w/punch mark at surface from 1999 tie out.

5-18-2005 County Surveyor found brass plug in good condition down 0.1'.

12-6-2007 County Surveyor found copper plug down 0.1' in good condition.