Certificate of Location of Government Corner

ID#: 522209 **Description:** SEC CEN 22 52 **Date Set:** 5/19/1986 **County:** Olmsted

Section: 22 **Township:** 105N **Range:** 12W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.

1/2" pipe w/cap RLS #14888

Reference Ties:

The corner falls 6' north of centerline of E-W twp road, 1' east of fence north, and 21' west of centerline of driveway north
The monument is down 1.1'
This corner is located by GPS measurement

Corner History:

4-25-1893 William Fraser, Deputy County Surveyor, (Book A, Pages 506-507, Survey No. 476) set stone at intersecting quarter lines. 1/16th North set limestone midway and on line at 20.12-1/2 chains (1328.25') to North 1/4. 1/16th South set limestone midway and on line at 19.86 chains (1310.76') to South 1/4. 1/16th East set stake midway and on line, no measurement given, to East 1/4.

5-31-1973 County Surveyor dug and found rectangular shape dark area with small limestone chips around the outside of this stone shape. RPs - Nail & Bottle Cap in east side PP S 33.5', SW corner concreted in corner gate post SE 41.15', Punch mark in top telephone cable marker post NW 31.25', Eye line of east edge large metal shed W 132.8', Center PP WSW 163.8'. 1/16th North dug and found limestone down 2' in good condition. The limestone falls just west of corner post to fences north, south, east, and west.

8-24-1978 County Surveyor 1/16th East dug and found only old wire and wood pieces indicating old fence was there.

5-19-1986 Vince Fangman set 1/2" pipe w/cap RLS #14888 at intersecting quarter lines.

6-2-1998 Vince Fangman found and used 1/2" pipe w/cap at intersecting quarter lines.

8-11-2003 GGG used computed center at intersecting quarter lines.

7-15-2009 County Survey Crew found 1/2" pipe w/cap down 0.7' in good condition.

7-20-2009 Vince Fangman found and used 1/2" pipe w/cap.

7-21-2011 County Survey Crew found 1/2" pipe w/cap down 1.1' in good condition and measured its position using GPS.

11-21-2014 Joel Thoreson, County Surveyor, recommends using the computed intersection of quarter lines for the center of section. Based on the county's section breakdown, the 1/2" pipe w/cap, as located by GPS in 2011, falls 0.17' north and 0.02' west of the computed center.

1-23-2015 Schwarz Surveying found and used 1/2" pipe w/cap at intersecting quarter lines.