Certificate of Location of Government Corner

ID#:522304 **Description:** 1/4 SEC COR 23 26 52 **Date Set:** 10/16/1978 **County:** Olmsted

Section: 23 **Township:** 105N **Range:** 12W **Monument Description:** Witness Corner: Cast Iron Cap on telspar pipe 60.0' West of corner on section line

Reference Ties:

Witness Corner:
Spike in N side 12" Walnut WSW 40.35'
County Survey Disk in fence post SW 7.0'
Spike in N side 8" Walnut SW 51.30'
County Survey Disk in NE side 24" blazed Maple SE 32.10'
Sign on fence post 7' SW
This corner is located by GPS reference stations "Calf A & B"

Corner History:

10-1853 Gov't Notes William A. Jones, Deputy Surveyor West on true line between sections 23 and 26. 40.00 chs. Set Quarter section post Linden 16 in. S10ºE 34 lks. Elm 13 in. N3ºW 92 lks.

5-1877 Thomas Hunter (Book A P. 312 No. 306), County Surveyor states that the corner was gone. He reset a stake from both bearing trees standing. He set the 1/16th East, the 1/16th West, the Center 26, and the 1/16th East of the Center 25, and the 1/16th West of the Center 26.

5-1877 Hunter (Book A P. 313 No. 307), County Surveyor, used this corner to set the Center 23.

10-16-1978 County Surveyor set this corner at the intersection of the line from the S. 1/4 Cor. 26 (set this survey see cert.) over a point at the Center 26 (which came in line with the fence South) located E-W at Hunter's prorated location between a stone found at the 1/16th West and a stone found at the 1/16th East and the line from Sec. Cor. 22-23-26-27 (set this survey-see cert.) over a stone found at the corner post at the 1/16th East. The corner came in a wide ditch so could not set a monument. Set a Cast Iron Cap on a square pipe as a Witness Corner 60.0' West on the section line. We dug at both the Center 26 and the Center 23 but did not find anything. The corner lines with the main line of fences East and West.

5-9-2002 County Surveyor found cast iron cap on telspar pipe witness corner up 0.1' in good condition.