Certificate of Location of Government Corner

ID#:522804 **Description:** 1/4 SEC COR 28 33 52 **Date Set:** 2/17/2009 **County:** Olmsted

Section: 28 **Township:** 105N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls under N-S fence line
Sign on fence post north 6 1/2'
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes William A. Jones, Deputy Surveyor West on true line between sections 28 and 33. 40.00 chs. Set a quarter section post. Red Oak 4 in. S6ºE 12 lks. Red Oak 7 in. N15ºW 2 lks.

4-1898 William Fraser (P. 621 No. 564), County Surveyor, found a marked stake by the fence corner. Set a 4"x5"x19" stone beside the stake.

2-1904 Charles Armstrong (P. 72B), County Surveyor, shows a stone at this corner.

10-14-1976 County Surveyor dug and found the recorded stone (broken) under the N-S fence. Set a CIM over a 1/2"x2' rod as the corner with the stone pieces on the North side.

2-17-2009 County Surveyor found CIM down 0.2' leaning. Took local ties and removed. Found 1/2" rod down 2.0' in good condition. Set a 6' telspar pipe w/CIC down 0.1' at rod location.