Certificate of Location of Government Corner

ID#:530104 **Description:** 1/4 SEC COR 1 12 53 **Date Set:** 3/1/2011 **County:** Olmsted

Section: 01 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Cap on Telspar Pipe

Reference Ties:

The monument is up 0.2'
Nail in SE side 10" Oak Tree NE 9.48'
CSD with concrete nail in N side of 6" Ironwood Tree SE 6.95'
Post with sign NNW 1.5'
This corner is located by GPS reference stations 530104 B and C

Corner History:

1854 Gov't Notes Michael Karrick, Deputy Surveyor West on true line between sections 1 and 12. 40.00 chs. Set quarter section post. Black Oak 13 in. N58°W 40 lks. Bur Oak 12 in. S50°E 54 lks.

7-1876 Thomas Hunter, County Surveyor, (P.301 No.296) states that the corner was missing. Both bearing trees were standing but the distances and bearings would not agree. Took the mean of the bearings and set a marked stake.

1-1893 William Fraser (P.504 No.474), County Surveyor, found a marked stake and both bearing trees. West set stakes 13.23 1/3 then 1.16 then 5.45 2/3 to stake assumed as 1/16 corner set M & L 19.85.

7-2-69 J. Kerr meas west from corner past assumed as probable line of corner of SE cor. 1 Pleasant Grove. Dug some for 1/16 stake. Meas to station 2430. All lines stopped. A wooded gulley with no fences any direction made any further work impractical abandoned line. Only way to reset corner means running line in early spring or late fall in cool dry weather record East 19.78 M & L or 2611.0. Meas West 873.7 + 76.55 + 340.3 + 1310.1 or 2599.8 no fences in any direction although a property corner of long standing. If center could be found the E-W line could be established as to its division point. Corner in roughest part of section.

1964 McGhie found vertical L stone likely washed that way on very steep slope. Very extensive survey. See survey (No good per card).

4-18-1977 County Surveyor found a 2-1/2"x15"x16" long limestone standing. Set a C.I.M. with a 12" piece of angle iron set on the West side of the bottom of the monument. Set the stone on the North side of the monument and piled limestone around the top of the monument.

3-1-2011 County survey crew found CIM laying on top of the ground. Found 12' angle iron in good condition. Also found nail in 10" oak (formerly 6" oak). Set 4' Telspar pipe with cast iron cap using the angle iron and nail in oak tree as reference ties.