Certificate of Location of Government Corner

ID#:530105 **Description:** SEC COR 1 2 11 12 53 **Date Set:** 10/4/2004 **County:** Olmsted

Section: 01 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

12" Poplar NW 23.3'
6" Poplar SW 7.1'
6" Oak NE 22.0'
Post w/sign 2' south
This corner is located by GPS reference stations "Ludwig B & C"

Corner History:

1854 Gov't Notes C. Karrick 80.00 set post for corner 1,2,11 & 12. White Oak 12 S 3'1 W 35. White Oak 10 W 55 W 61. White Oak 10 W 25 E 97. Black Oak 8 S 65 E 35.

1-1893 W. Fraser P 504 No. 474 found stone and stake claimed as set from original corner. All bearing trees gone but 1 stump did not quite agree with it but left as is as there were 3 other bearing trees to guide corner. Each set corners at 19.85 then 5.45 2/3 then 1.16 then 13.23 1/3 to N 1/4 12 a stake. South 16.34 5/8 then 3.47 7/8 to 1/16 cor. Then 19.82 1/2 to W 1/4 12 set M & L.

1938 county highway department (Bk 96) found stone in highway layout.

8-1940 J. Kerr B. 20 P. 62-65 used corner. Measured North 2619.62 to set 1/4 1-2 1" x 3' pipe. Measured West 2640.52 to set 1/4 2-11 1 1/4" pipe glass etc.

5-10-1951 J. Kerr found 3"x6" Limestone 12" above ground and left as found. RPs- McGhies; 12" poplar NNW 23.3, 6" poplar SW 7.1, 6" oak NNE 22.0, 10" W oak N 126.2.

1966 county highway department B. 307 found 3" x 5" limestone up 10" ± with iron pipe by side. 1" pipe on section line 550' North as P.I.

8-19-76 County Surveyor (1/16 E) found stake on N. side of stubs of two old fence posts (removed stake to office). Drove 1" x 2' shaft in stake hole. Corner 1' W of fence N. and in line with fence W but 4' N of tree acting as corner post. R.P.'s: Spike and CSD in 18" blazed Oak NW 27.34 Spike and CSD N side blazed 9" Oak (most nthly of twin) NE 16.37.

10-04-2004 County Surveyor found 3"x6" topped limestone up 1' in good condition. Removed 3"x6"x36" stone and set 5' telspar pipe w/cast iron cap up 0.3'. Set post w/sign 2' south.