Certificate of Location of Government Corner

ID#:530204 **Description:** 1/4 SEC COR 2 11 53 **Date Set:** 7/29/1968 **County:** Olmsted

Section: 02 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 36' east of centerline of residential driveway on curve
County Survey Disk in W side 24" Oak up 2.0' NNE 47.04'
SE corner of concrete garage foundation SW 136 1/2'
Post w/sign 15' east
This corner is located by GPS measurement

Corner History:

5-19-1854 Gov't Notes West on true line between 2 & 11 Var. 10° 8' 40.00 set quarter sec. Post. Br. Oak 8 N 45 E 99 lks=65.34'. Br. Oak 7 S 65 E 106 lks= 69.96'. 80.00 section corner.

8-1940 J. Kerr (B. 20 P. 62-65) Sections 2-3-9-10 run line set 1 1/4" pipe broken glass M & L 2640.52 some glass well below ground around pipe. 10" White Oak marked S. 1/4 2 N 10 1/4°E 47.1. 7" White Oak marked S 1/4 2 N 57°30E 29.2

7-29-1968 J. Kerr found iron pipe and glass in open field. Measured from center 2621.1 shellrock within 2' set sash weight in place of 1 1/4" pipe with short C.I.M. over weight. Corner 1 foot dup. Hub & 20d South side 18" White or Burr Oak blazed AZ 850°5' 59.95. Hub & 20d East side 12" Burr Oak used blazed slope meas as terminal for fences North and West AZ 17°16' 46.8. 1 1/4" pipe driven to rock, up 6.6' on exact N-S 1/4 line North 44.25. 1/16 corner between center 2 and S 1/4 s. Set 1/2" x 18" rod on line and midway 1310.55. Corner comes within 2' of East edge road surface 95.5' to center huge rock on North side farm drive 82.0 to center 20" Oak about 15' South of East.

10-6-2004 County Surveyor found CIM in good condition down 0.9'. Took new ties due to new home construction. Set sign and post 15' east on edge of woods.

4-13-2007 WHKS & Co. found monument in good condition.