Certificate of Location of Government Corner

ID#:531105 **Description:** SEC COR 10 11 14 15 53 **Date Set:** 8/19/2003 **County:** Olmsted

Section: 11 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' south of fence west and 2' west of centerline of CR 116
County Survey Disk in N side PP #44631 WNW 41.16'
County Survey Disk in NW side PP #44596 NE 53.47'
This corner is located by GPS measurement

Corner History:

Gov't Notes 80.00 set post corner to sections 10-11-14-15. White Oak 15 S 40 W 21. Aspen 8 N 68 W 37. Aspen 12 N 64 E 31. White Oak 14 S 60 E 5.

9-1893 W. Fraser (P532 No.495) found stake, tested stump SW B.T. set stone beside stake. 1/16 East set stone and stake M & L 19.98 then drove stake 9.99 M & L between above 1/16 & 1/4 cor.

1-1894 W. Fraser (P.543 No.504) found stone and stake. 1/16 South drove iron stake M & L 19.87 1/2 see 1/4 10-15 for plat. (see 1/4 14-15 for 1/16 S).

8-1940 J. Kerr (B20 P.62-65) found recorded stone packed in stone 2 x 4 x 18. Notch in 10" elm NE 49.95 (see B-8 P.19-21). Center 7" Ash SW 70.6. Center 9" red oak W 37.8. Corner 3.5' W centerline road 5242.75 from sec cor 1 mile N.

7-26-1968 County Surveyor found stone and iron shaft as recorded. RPs- corner lies 1.0' south of fence west and 2 ± west centerline road, disc top 12" white oak corner post east 28.7, knotch in root south side 18" elm ENE 50.2, natural crease in 20" white oak NE 84.05, cap in pp# 13195(5' north of west 41.1).

1-22-1985 McGhie & Betts found C.I.M. Measured 2629.99 West to dragtooth a 1/4 Cor. 10-15 and 1310.31 North to 1" pipe @ 1/16 North. Surveyed SE 1/4, SE 1/4, SE 1/4 sec 10.

8-19-2003 County Surveyor found 120d spike down 0.2'. Took local ties and removed. Found CIM down 1.1' in good condition which matched ties of spike. Removed CIM and found a sash weight down 2.8'. Removed weight and found a 1" iron shaft down 3.8'. Set CIC on a 6' telspar pipe over the 1" iron shaft down 0.5'.

4-13-2007 WHKS & Co. found monument in good condition.