Certificate of Location of Government Corner

ID#:531204 **Description:** 1/4 SEC COR 12 13 53 **Date Set:** 12/3/2009 **County:** Olmsted

Section: 12 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

Corner center 18" tree used as fence runs northerly & southeasterly N 49.3'
Spike in NW side 9" Oak SW 10.89'
Spike in N side 12" Oak W 22.53'
This corner is located by GPS reference stations "531204 C & D"

Corner History:

1854 Gov't Notes Michael Karrick, Deputy Surveyor, West on true line between sections 12 and 13. 40.00 chs. Set quarter section post. Bur Oak 18 in. N20°W 34 lks. Bur Oak 12 in. S55°E 45 lks.

1-1872 Thomas Hunter, County Surveyor, (P.190 No.201) found the corner standing and tested with the bearing trees. Set a stake at the Center 13.

2-1874 T. Hunter found the corner and bearing trees as P.190. Found the stake at the Center 13 and set the 1/16th South of the Center 13.

1-1894 William Fraser (P.541 No. 502) found the stake at the Center 13 and set a stone there.

1964 McGhie set a 1" pipe on line from an iron wagon hub found at the 1/16th South of the Center 13 over a stone found at the Center 13.

4-28-1975 County Surveyor found the 1" pipe set by McGhie.

4-12-1977 County Surveyor set a Cast Iron Cap on a square pipe as the corner on the line from the S 1/4 corner 13 over a stone found at the Center 13 and in line with an old fence going East. McGhie's pipe was gone but found the hole where it stood 3.1' South and 2.7' East of the CIC.

11-5-2009 County Surveyor found cast iron cap on telspar pipe up 0.4' leaning south.

12-3-2009 County Surveyor found cast iron cap on telspar pipe up 0.4' leaning south. Plummed up monument and checked tie, matched within 0.01'. Drove pipe down to surface and reset cap at plummed location.