Certificate of Location of Government Corner

ID#: 531805 **Description:** W SEC COR 18 19 53 **Date Set:** 10/18/2007 **County:** Olmsted

Section: 18 **Township:** 105N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 11 1/2' west of centerline of CSAH 20 on curve and 23' south of centerline of field entrance west
The monument is at the surface
Top SW corner S end retaining wall SE 50.33'
This corner is located by GPS measurement

Corner History:

8-12-1853 J. Ball, Deputy Surveyor, 80.00 chains set corner post to sections 13-18-19-24. Built mound of earth and sod, pit 8 links (5.28') south, planted osage orange seeds SE and apple seeds NE. RPs - 5" Black Oak N 4° E 12 links (7.92'), 5" Black Oak S 50° W 36 links (23.76')

6-26-1876 T. Hunter, County Surveyor, (Field Book 4, Page 138-139) found and used stone, set by Mr. Freeman, surveyor, 5 or 6 years ago, in unrecorded survey.

6-4-1886 T. Hunter, County Surveyor, (Field Book 14, Page 62) indicates corner in an unrecorded survey.

6-10-1886 T. Hunter, County Surveyor, (Book A, Pg. 411, No. 400) found stone with old stake by its side in center of road. Accepted stone and stake as corner.

11-1941 County Highway Department (Bk. 137, Pg. 4, 53 & 56) dug all around corner location and found nothing. Road has been graded several times at this location and looks as if it might have been graded out. J.L. Conley, who owns and has lived on the 1/4 section NW of this corner, avers a stone monument was here for many years and that he placed his fence post 33 feet west. Set 2"x2" stake on line from NW Section Corner 19 over W 1/4 Corner 19 and in line with fence west. RPs - Disc in Oak SE 56.2', Hub NE 78.4'

8-3-1964 J. Kerr, County Surveyor, found hub & nail used by County Highway Department. Set Cast Iron Monument over steel rod at County Highway Department hub location. RPs - Disc in large cedar CP WSW 34.05', Center 4" Iron Shaft Cemetery CP E 39.15', Center 4" Iron Shaft Cemetery CP NE 121.70', NW corner of base August Schormstein gravestone NE 67.35', 3/4" iron stake in woods ESE 65.73'

3-31-1967 County Highway Department (Bk. 323, Pg. 4) found CIM and took ties. RPs - Spike & Disc in FE NW 49.54', Spike & Disc in CP W 31.67', Spike & Disc in 24" Oak ESE 55.97', NW corner of base August Schormstein gravestone NE 67.35'

9-17-1970 County Highway Department (Bk. 323, Pg. 5) found CIM and referenced location. RPs - 2"x2" hub on line to top headstone SE corner of cemetery (Katherine Engel) E 48.87'

9-21-1971 County Surveyor found nothing. Corner destroyed in extensive road change. Set 1/2" rod in road and took ties. RPs - New 60d spike in SW side 24" Oak ESE 56.18', 3/4" iron stake in woods ESE 65.73', Center 4" Iron Shaft Cemetery CP E 39.15', Center 4" Iron Shaft Cemetery CP NE 121.70', South corner of footing of retaining wall E 34.0'

10-10-1972 County Highway Department (Bk. 323, Pg. 4) found 1/2" rod. RPs - Iron stake ESE 65.73', Base 4" iron post E 39.15', Base 4" iron post NE 121.70'

10-25-1991 County Survey Crew found 1/2" rod and set 1" square pipe w/cap over rod. Corner falls 12-1/2' west of centerline of CSAH 20 and 24' south of centerline field entrance west. RP - SW corner south end retaining wall SE 50.34'

1-17-2002 County Survey Crew found 1" square pipe w/cap in good condition and located its position using GPS.

3-14-2005 County Survey Crew found 1" square pipe w/cap at surface in good condition.

6-1-2007 County Survey Crew found 1" square pipe w/cap at surface in good condition. Tied out corner for 2007 road overlays.

8-29-2007 County Survey Crew removed 1" square pipe w/cap for 2007 road overlays.

10-18-2007 County Survey Crew set 1" square pipe w/cap at surface at referenced location.

9-27-2012 County Survey Crew found 1" square pipe w/cap at surface in good condition.