Certificate of Location of Government Corner

ID#:532306 **Description:** 1/4 SEC COR 22 23 53 **Date Set:** 8/18/1982 **County:** Olmsted

Section: 23 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 2' south of centerline of CR 139 and 2' east of fence north
County Survey Disk in CP NNW 41.42'
County Survey Disk in PP #13135 SW 73.85'
This corner is located by GPS measurement

Corner History:

5-1854 Gov't Notes Michael Karrick, Deputy Surveyor, North between Sections 22 & 23. 37.75 chs. Creek runs NE 40.00 chs. Set quarter section post. Bur Oak 9 S53W 568 lks. Bur Oak 12 S47E 238 lks.

4-1856 E.P. Bircher, Surveyor, per T. Hunter, Deputy, (Old Road Book, Road No.3) surveyed a road in Sec. 22 which ran from the Center 22 on the E-W 1/4 line to the 1/16 East (19.50 chs.) and then North to the North line of Sec. 22.

2-24-1870 Robert Perry, County Surveyor, per S. Freeman, Deputy County Surveyor, (Book A, Page 102, No. 142) "W quarter post (Sec. 23) standing. Bearing tree S&W standing--The other S&E cut--Stumps remaining, marks visible--notes correct." He used the corner to set the Center 23 (no description).

6-1886 Thomas Hunter, County Surveyor, (Old Fieldbook 14, Page 64) may have used this corner (no description) to set the Center 22 and the 1/16 West of the Center 22.

4-1895 William Fraser, County Surveyor, (Book A, Page 563, No. 517) "Could not find the corner at this 1/4 post and no evidence to locate the same, so planted stone and also an iron stake as corner on line and midway (39.88 chs.)" between the section corners. He used the corner to set the 1/16 South, a stone and stake, midway (19.94 chs.) and on line to the SW corner 23, a 15x4x4 inch stone set this survey. He also set the 1/16 East, a temporary stake, midway (19.75 chs.) and on line to the Center 23, a stake, set at intersecting 1/4 lines.

2-1896 William Fraser (Book A, Page 591, No. 537) found corner set in Survey No. 517, Page 563. He used the corner to set the 1/16 North, a stake not marked, midway (19.94 1/2 chs.) and on line to the NE corner 22 (Found corner set in Survey No. 517). He also set the Center 22, an iron and wood stake, at intersecting 1/4 lines. He set the 1/16 West of the Center 22, a drag tooth, on line and midway (20.13-1/2 chs.) to the W 1/4 corner 22.

7-19-1972 County Surveyor dug at double the line and measure from the SE corner 22 (CIM over Fraser's stone found 1972) over the 1/16 North (Fraser's stake and stone found) but could not find corner. Completed line to 1/4 22-23, set nail & dug test hole to see if any soil left where corner may be. RPs to nail- POT nail west on line 48.13, 16D 4' W of N west side corner post 38.82, 16D SW on NW side corner post 63.21. Set 1/2"x3' iron as 1/4 22-27.

7-22-1982 County Surveyor dug again on the line from the W 1/4 corner 22 (CIM where cedar stake found in 1972) over the Center 22 (pipe over iron pin found in 1972) which came appx. 2.2 South of 1972 location using the 1/16 South. Could not find corner. Dug through 5-1/2' of fill to bedrock.

8-18-1982 County Surveyor set a Cast Iron Monument over a 3/4" rod as the corner at the intersection of the line from the W 1/4 corner 22 over the Center 22 and the line from the SE corner 22 to the NE corner 22 as set in 1972 (See Cert. filed). Measured North 2633.47 to the NE corner 22 and 2631.21 South to the SE corner 22. The stake and stone found at the 1/16 South in 1972 is .24 East and 1.09 North of the midway and on line location by our electronic traverse comp. Measured East 2605.94 to an iron found at the Center 23 in 1972. We reset the E 1/4 corner 23 in this survey--it could not be found.

11-13-2009 County Surveyor found CIM down 0.8' in good condition.