Certificate of Location of Government Corner

ID#:532704 **Description:** 1/4 SEC COR 27 34 53 **Date Set:** 8/10/1982 **County:** Olmsted

Section: 27 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 2 1/2' SW of CP to fences north and east
County Survey Disk in W side PP SSE 2.65'
Survey sign on PP 2 1/2' south
This corner is located by GPS measurement

Corner History:

5-1854 Gov't Notes Michael Karrick, Deputy Surveyor, West on true line between sections 27 and 34. 40.00 chs. Set quarter section post inmound with trench, pits, and charred stake and Osage Orange seeds NE & SW 80.00 chs. To Section Corner.

1950's TH 30 R/W Map--- accepted fence intersection as 1/4 corner location. Found no other survey records of this corner.

8-5 & 20-1982 County Surveyor dug at the Center 34 and the Center 27 but did not find anything.

8-10-1982 County Surveyor dug with the backhoe on the West side of the corner post to fences North and East (also lines with fence South across TH 30.) Found remaining 12" of stake with wood pieces and perfect tappered point extending into clay subsoil. Top of stake down 3'. Drove 1" square pipe in the stake hole and set a square pipe with a Cast Iron Cap at the ground surface.

11-6-2009 County Surveyor found cast iron cap on telspar pipe down 0.1' in good condition.