Certificate of Location of Government Corner

ID#:533005 **Description:** W SEC COR 30 31 53 **Date Set:** 10/18/2007 **County:** Olmsted

Section: 30 **Township:** 105N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in line with fence west, in centerline of CSAH 20 and 2' north of centerline of twp road east
County highway disk in NE side PP #42588 SE 67.95'
Traverse point Payne W 82.89'
Ref iron E 145.17'
This corner is located by GPS measurement

Corner History:

Gov't Notes 80.00 set post and drove charred stake corner to sections 25-30-31-36. Built mound and trench. Planted S.E. osage and NE apple seeds.

7-7-1965 J. Kerr found 1/2" steel rod and placed cast iron monument over 1/2" steel rod.
RPs- disc in PP SE 53.41, disc in top of tlele riser post NW 44.84, corner lies in line with fence running west, corner lies in center road running north & south, corner lies 2.0' north center road running east.

6-21-1988 County Surveyor found CIM in good cond. Down 12" in gravel road.

5-31-1989 County Surveyor set RP iron 1/2" rod in centerline road east and on line Payne over W 30,31 to RP iron.

10-17-1991 County Surveyor set 1" square pipe w/cap in new blacktop from transit ties. (See card for ties.) RPs-Corner lies in line with fence running west, Southeast disc in power pole #42588 67.87', Disc in top of telephone riser post NW 44.84'.

6-11-2002 County Surveyor found 1" square pipe w/cap at surface in good condition.

6-1-2007 County Surveyor found 1" square pipe w/busted cap at surface in good condition. Tied out corner for 2007 overlays.

8-29-2007 County Surveyor removed 1" square pipe w/cap for 2007 overlays.

10-12-2007 County Surveyor set mag nail at surface from 2007 overlay tie out.

10-18-2007 County Surveyor set 1" square pipe w/cap at surface over mag nail.