Certificate of Location of Government Corner

ID#: 541306 **Description:** 1/4 SEC COR 13 14 54 **Date Set:** 7/11/2005 **County:** Olmsted

Section: 13 **Township:** 105N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls under N-S fence and 1' north of square brace post
Sign in brace post 1' south
This corner is located by GPS reference stations "Halstead A & B"

Corner History:

1853 Gov't Notes Yerby 40.00 Set post to corner for sect. 13-14 in mound of sod & earth deposited charcoal made trench pitts planted Osage Orange seed E & W of trench.

± 1958 MHD used Cor. fe post as 1/4 cor. Meas. W to Cen. 14 (Fe line & Rd inter.) 2665.1', Meas. N to 11-12-13-14 (road inter. only) 2640.0'.

11-5-1984 County Surveyor dug from point 39.0± (line from W 1/4 14 over 1/16 E (fd) North of t.n. and under N-S fence, for 3' North, 2-1/2'+ South, 2' West, and 2-1/2' East by 1-1/2 to 2' deep to clay. 39.0 North came .5 North of RR tie fence post in N-S fence could not find evidence of old c.p. as called for by Hunter, but there was some knarred wire. c.p. possibly dug out when present post set. Found a 5"x7"x12" boulder (down 6") and standing under N-S fence. The were some wood pieces by the stone and under the stone, but gopher had dug directly under the stone so there was black dirt and a soft spot under the stone but not a definite stake hole (See Drwg-Railroad location - Survey) We also found the remains of a small stake - 2" claim by 9" long reaching into clay and standing 1/2' East of N-S fence (See Drwg-Railroad location - survey).

9-12-1989 MHD fd nail with head gone in center of N-S Rd & in line of fence west, probably nail set in 1971.9-12-1989 Fd nail with head gone in center of N-S Rd & in line of fence west, probably nail set in 1971.

9-23-2003 V. Fangman used mathematical position from County Surveyor at quarter corner location.

7-11-2005 County Surveyor set 5 1/2' telspar pipe w/cast iron cap up 0.2' from GPS and traverse data. Set sign in brace post.