Certificate of Location of Government Corner

ID#: 541404 **Description:** 1/4 SEC COR 14 23 54 **Date Set:** 4/23/1996 **County:** Olmsted

Section: 14 **Township:** 105N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 2' west of centerline of old abandoned road
County Survey Disk in PP #9478 NE 85.40'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes Yerby 40.00 set temp 1/4 sect. Post West on true line between sects. 14 + 23 V7° 14' E. 40.12-1/2 Set 1/4 sect. Post in mound of earth & sod, deposited charcoal & made trench pitts planted Osage Orange Seed N & set trench.

5-1874 T. Hunter p.244 No. 245 could not find corner. Set stake in road in line of old rail fence running east claimed set on line with old stake and 2 rods west of east road fence. (Now county road some cut in grade, corner lost.)

10-1924 County Highway Department B43 P.3 No disc of any corner. PI set at Sta 145 + 96.3 Delta 0°06' rt going south. Stake NE 49.2 - Stake SE 49.3 Sta. 1/4 26-35 251+85.3 10589.0 or 5294.5 (2647.25) Meas record 1/4-26-35 north to center 26 - 2646.6 (only record).

11-28-1975 County Surveyor set 5/8"x15" rod midway between Sec. Cor. 14-15-22-23 and temp. corner at 13-14-23-24 and in line with fence W Corner 2' W of centerline N-S road and 1' E of 1" x 2" stake found the year before.
R.P.s CSD E side PP #9478 NE 83.15 Nail S. side corner post W 21.15 - Corner not Final since 13-14-23-24 reset find.

9-24-1984 County Surveyor, Fd 5/8" re-rod set 11-28-75 bent over bad. Corner post R.P. West now gone.

9-25-1984 County Surveyor, set a 1" square (O.D.) pipe from 1975 P.O.T. (Fd spike, replaced with 5/8") North of corner (Drwg 3-5). Turned angle rt. 178°55'58" from N 1/4 14 for 388.00 Pt. Came at location of bent rod found. Note: Corner to be reset after finding Hunter's stake at the 1/16 West of Center 14.

2-9-1988 County Surveyor decided to use N-S 1/4 line in Section 14 & line of fence West as location, this comes 5.13' West of 1984 location, will set mon later.

4-23-1996 County Surveyor found 1" square pipe set in 1984 badly bent. We pulled the pipe and located hole by traverse to check position. We then set up final position 5.13' West of M & L point. This final location is on the T. Hunter 1/4 line from the North & line of fence West. Set cast iron cap on telspar pipe as corner ±2' West of traveled centerline old abandoned road. CSD in PP #9478 NE 85.4'. No longer any fence or ridge West.

1-17-2002 County Surveyor found cast iron cap on telspar pipe down 0.3' in good condition.

11-20-2003 County Surveyor found cast iron cap on telspar pipe down 0.1' in good condition.