Certificate of Location of Government Corner

ID#: 542504 **Description:** 1/4 SEC COR 25 36 54 **Date Set:** 6/25/2013 **County:** Olmsted

Section: 25 **Township:** 105N **Range:** 14W **Monument Description:** Cast Iron Cap on Telspar Pipe

Reference Ties:

The monument is at the surface
The corner falls 2 south of remnants of E-W fence
Post with sign 2' north

Corner History:

1853 Yerby 40.00 chains set 1/4 section post in mound of earth and sod. Deposited charcoal. Made trence and pits. Planted Osage Orange seed north and south

9-4-2012 County survey crew visited area. Found steel fence corner post with pieces of wire running E-W and S.

6-20-2013 County survey crew excavated area around the fence corner post using a backhoe. Found remnants of wood post and wire and some small stones. It did not fit the lost survey position or the current field occupation line south which is not well defined.

6-25-2013 County survey staff computed a lost postion midway and on line from the southwest corner to southeast corner of section 25. County survey crew set 4' telspar pipe with cap at the computed location.