Certificate of Location of Government Corner

ID#: 542704 **Description:** 1/4 SEC COR 27 34 54 **Date Set:** 7/19/2002 **County:** Olmsted

Section: 27 **Township:** 105N **Range:** 14W **Monument Description:** 5/8" copper plug w/punch mark

Reference Ties:

The corner falls in centerline of TH 63 and in centerline of CSAH 35 west
Top Hyd Nut ENE 128.76'
W end of concrete surface 10th Ave E 77.65'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes: 40.00 chs. Set temp. 1/4 section post. West on true line 40.25 chs. Set a 1/4 section post. Burr Oak 12 in. N77°E 123 lks. Burr Oak 10 in. S83°E 177 lks.

10-1904 C. Armstrong P94B S 33. A Tubbs, L. Albright, Thas Kelly, Albert Ringy found stake , stone, and iron bar at North Quarter Corner Section 34 and stake at 1/16 corner West on proving Northeast Corner 33 tested by bearing tree.

10-1905 C. Armstrong P96B Northwest Quarter Section 34. Mrs. F. McCall found stone and witness tree.

4-1917 County Highway Department, Book No. 16 P. 46 shows a corner used. Ties - telephone pole NE 31.8 tree N.W. 36.7

4-1970 Roger Brand, county surveyor, found chisel "+" and nail in concrete pavement center line as North Quarter Corner Section 34 which Minnesota Highway Department right-of-way map shows as Quarter Corner used by them.

4-29-92 Yaggy Colby Associates found a chiseled hole in concrete in center line T.H. 63, which proved to be accepted Quarter Corner. Yaggy Colby Associates tied Quarter Corner to two separate traverse stations to assure Quarter Corner would be reset properly in the fall of 1992 after T.H. 63 reconstruction.

11-25-92 North Quarter Corner was destroyed during construction the summer of 1992. Yaggy Colby Associates set a chiseled hole with cross at the same location as previously located by Yaggy Colby Associates.

7-19-2002 County Surveyor set 5/8" Copper Plug w/punch mark at drill hole position at surface.