Certificate of Location of Government Corner

ID#: 543204 **Description:** S 1/4 SEC COR 32 54 **Date Set:** 7/2/2007 **County:** Olmsted

Section: 32 **Township:** 105N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 119 1/2' NNW of centerline of CSAH 6 on curve
County Survey Disk in NE side PP SE 29.76'
Post w/sign 2' north
This corner is located by GPS measurement

Corner History:

5-10-1878 Hunter (Book A, Pg. 343, No. 337) found the corner gone and he reset a stone 4" by 10" by 16".

12-14-1915 J.Kerr (Book B, Pg.242 and Field book 11 Pg.23) Found corner.

6-25-1971 County Surveyor set drag tooth below stone with CIM above 5" deep. RPs- Conc. Nail on NE side PP #11022 29.2, MHD disc in S side TP ENE 86.46, concrete nail thru Hires cap E side PP #11023, PP with tansfrormer in farmyard E of N 141.25, corner lies 3' or 4' north of center old road west.

11-6-2001 County survey crew found CIM down 0.3' in good condition.

9-29-2005 County survey crew found CIM down 0.4' in good condition.

1-4-2006 County survey crew found CIM down 0.5' in good condition.

7-2-2007 County survey crew found CIM w/o head down 0.5' with slight lean SE. Removed CIM and found 4"x10"x11" stone down 1.6' in good condition. Removed stone and found drag tooth down 2.4' in good condition. Removed drag tooth and laid out corner from control coordinates which matched drag tooth. Set 5 1/2' telspar pipe w/cast iron cap down 0.2'. Set post w/sign.