Certificate of Location of Government Corner

ID#: 543405 **Description:** S SEC COR 33 34 54 **Date Set:** 10/6/2005 **County:** Olmsted

Section: 34 **Township:** 105N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 6 and 81 1/2' east of east edge of concrete of BR. #55573
County Survey Disk in guard rail post SW 29.17'
County Survey Disk in guard rail post NW 29.16'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes: West on south boundary Section 34 80.00 chs. Set corner post. Burr Oak 20 in. N35°W 207 lks. Burr Oak 16 in. N80°E 69 lks. .4

4-29-1875 Thomas Hunter (Book A, P271 No. 269) County Surveyor, found stake and stone on standard parallel in the center of the road. Bearing trees gone, but a Mr. Woolridge and a Mr. Knapp aver they had watched and preserved this corner.

6-8-1892 Thomas Fraser (Book A, P487 No. 413) County Surveyor, found stone.

8-7-1974 Roger Brand, County Surveyor, reset this corner in center of County Road 6 since this is where McGhie & Betts, Inc. had set their corner previously, and at Hunter's prorated measurement which moved the corner 7-1/2' east of McGhie's rod. Set cast iron monument over an iron rod. RP- CSD disc on the NE side of pp# 11056 NW 46.3, E end conc.deck in centerline CR# 6 W 131.27.

3-5-1992 Yaggy Colby Associates found a cast iron monument set by Roger Brand 8/7/74 in the center of County Road 6 ± 0.8' below bituminous surface.

11-06-2001 County survey crew found CIM down 1.1' in good condition.

7-7-2004 County survey crew found CIM down 1.1' in good condition. Tied out corner for road and bridge construction.

10-6-2005 County survey crew set 1" square pipe w/cap at surface from 2004 tie out.

9-21-2007 County survey crew found 1" square pipe w/cap at surface in good condition.