Certificate of Location of Government Corner

ID#: 543605 **Description:** S SEC COR 35 36 54 **Date Set:** 7/2/2007 **County:** Olmsted

Section: 36 **Township:** 105N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 20' west of centerline of N-S twp road and in line with fences east and west
Fresca cap in S side PP W 19.32'
County Survey Disk in NE side PP NW 9.74'
Post w/sign 1' south
This corner is located by GPS measurement

Corner History:

5-1902 T.Fraser Pg.16 B; Set stone .

12-1910 C.Larson Pg.144B; found stone.

7-1930 county highway department Bk.57 Pg.41; found boulder.

8-25-1971 County Surveyor set car axle with gear as corner. Corner came in center bottom of ditch on W side of N-S road. RPs- shaft and gear as set in bottom ditch in line fence E-W 19.5 just S of W to fresca cap on S side 3 phase pp, 9.3 NW to Dads rootbeer cap on NE side regular pp# 15356.

5-15-1995 County Surveyor found auto axle with gear in good condition. Set sign & post 1' south.

1-19-2001 County Surveyor found auto axle with gear up 0.3' in good condition.

6-11-2002 County Surveyor found auto axle with gear in good condition.

7-2-2007 County Surveyor found axle shaft up 0.3' in good condition, took local ties and removed. Set 6' telspar pipe w/CIC up 0.3' from ties. Updated ties.