Certificate of Location of Government Corner

ID#: 551205 **Description:** SEC COR 11 12 13 14 55 **Date Set:** 10/24/1996 **County:** Olmsted

Section: 12 **Township:** 105N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 15 and in centerline of E-W twp road
County highway disk in SE side PP SW 53.52'
Punch hole in 18" CMP NW 39.77'
County highway disk in top 6" Cedar CP SE 59.8'
Ref pipe E 93.00'
This corner is located by GPS measurement

Corner History:

5-1853 Gov't Notes M.G. Karrick, Deputy Surveyor North between sections 13 and 14. 80.00 chs. Set a post for corner Br. Oak 15 in. S34°W 1070 lks. Dug trench.

3-1858 J. Fellows (P.51 No. 74) used this corner.

9-1913 D. Williams (P.228 Book B), County Surveyor, could find no knowledge or evidence of the corner. Used a point in center of road as corner.

1960 county highway department (B.242 P.3) assumed corner and took R.P.'s

5-1972 County Surveyor set a nail in center line CR 15 from 1960 County Highway Department references.

4-24-1974 County Surveyor set a CIM over 1/2"x6" rod at the location of nail set in 1972 since have no further evidence to prove corner location.

6-28-1996 County Surveyor found CIM in good condition. Set Ref pipe on North shoulder 80th St SW East of CR 15. Ref pipe is 11' North of centerline 80th St.

7-2-1996 County Surveyor removed CIM.

10-24-1996 county highway department set 1" square pipe w/cap at surface from 1996 overlay tie out.

6-28-2007 County Surveyor found 1" square pipe w/cap at surface in good condition.