Certificate of Location of Government Corner

ID#: 551304 **Description:** 1/4 SEC COR 13 24 55 **Date Set:** 8/20/2003 **County:** Olmsted

Section: 13 **Township:** 105N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The monument is down 0.4'
The corner falls in centerline of TH 30 and 5' east of fence south
County Survey Disk in W side PP #7093 SE 88.42'
This corner is located by GPS measurement

Corner History:

5-1854 Michael Karrick 40.00 set quarter section post. Burr Oak 18 S 50 W 75. Burr Oak 12 N 43 E 170.

3-1858 John Fellows (P.51 No.74 S.13) used corner. East 1/16 19.99. West 1/16 19.96. North 39.80 very indefinate.

4-1878 Hunter (P.335 No.329 S.24) Hans Amundsen, etal. Corner gone, no evidence or knowledge of it. Set stake "well down" M & L 40.04 1/2 (S 88 1/2 E). 1 1/16 West and East stakes M & L 20.02 1/4 (S 88 1/2 E). 1/16 South set stake M & L 20.00 3/4 (N 1° 20' E). 1/16 center NW and NE 1/4 set stakes inters lines. Minn State Hwy 30 Const Notes. Station 289 + 85.2 to line fence running South making 2639.4 West to staion at 13-14-23-24. Centerline State Hwy 30 lies 6.2' North of section line as built. Evidently used straight line between section corners or center old road or just plain assumed.

1986 Vince Fangman set 1/2" pipe M & L.

8-20-2003 County Surveyor found 60d spike down 0.3', removed and found 5/8" pipe w/cap destroyed. Took local ties and removed. Set 1" square pipe w/cap at surface from ties. CSD w/concrete nail in West side of PP #7093 88.42' SE. Monument falls in centerline of Mn/DOT Hwy #30 and 5' east of fenceline south.

9-5-2006 County Surveyor found 1" square pipe w/cap in good condition at surface.

4-26-2013 County survey crew found 1" square pipe with cap at surface in good condition. Lowered pipe and cap 0.4' in preparation for 2013 road overlay.