Certificate of Location of Government Corner

ID#: 551306 **Description:** 1/4 SEC COR 13 14 55 **Date Set:** 10/24/1996 **County:** Olmsted

Section: 13 **Township:** 105N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 10' east of centerline of CSAH 15, 15 1/2' south of centerline of field entrance east and in line with fence west
Red head spike in top fence post E 38.06'
Top of L iron CP W 60.79'
Ref pipe NE 43.64'
This corner is located by GPS measurement

Corner History:

5-1854 Michael Karrick 40.00 set quarter section post. Burr Oak 18 S 50 W 75. Burr Oak 12 N 43 E 170.

3-1858 John Fellows (S.13 P.51 No.74) used corner 1/16 East 19.96. 1/16 North 20.01. 1/16 West 19.71 or 19.91.

1960 county highway department (B242 P3) assumed corner. Hub W 51.0. Hub SW 59.86. Hub NW 54.33. Std 236 + 02.5 PI delta 0° 29' Rt from S meas South to center line 30 Hwy 2602.5.

6-30-1992 County Surveyor set 1" square pipe/cap M & L corner falls inline of fence West and ± 10' East of centerline of N-S CR # 15 RP's centerline filed drive East, North 15 1/2' face at top of L iron. Corner post to fences N-S-W West 60.79.

6-28-1996 County Surveyor found 1" square pipe w/cap in good shape, set Ref pipe w/cap on North edge field drive NE of cor. Angle at Ref pipe. Angle Rt P.K. nail in P.P. #6999 (1st pole South of cor. On East side CR # 15) to 1/4 cor. 13-14. 56± 41 34" to 1/4 cor. 13-14 HOR 43.64. RP to 1/4 cor. Red head spike in top fence post East 38.06.

7-3-1996 County Surveyor removed pipe w/cap.

10-24-1996 county highway department set 1" square pipe w/cap at surface from 1996 overlay tie out.

6-28-2007 County Surveyor found 1" square pipe w/cap at surface in good condition.