Certificate of Location of Government Corner

ID#: 551806 **Description:** W 1/4 SEC COR 18 55 **Date Set:** 9/10/1984 **County:** Olmsted

Section: 18 **Township:** 105N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' east of N-S fence and E-W fence now mostly down
The monument is up 0.5'
Post w/sign 2' north
This corner is located by GPS measurement

Corner History:

10-1853 John Ball 40.00 Set post for quarter sec. corner Burr Oak 12 S 50° E (311) links. Burr Oak 5 N 38° W 213 links. Dug trench per instructions.

6-1895 W. Fraser (P.581 No.530 S.18) Al Aaby, E. Skjervan found stake and post in mound, left as is. Used corner only to set center and a corner 10 chs West of center. A boulder stone on line of E-W 1/4 line.

9-10-1984 Olmsted County Surveyor dug under N-S fence on W Fraser line from E 1/4 18 over center 18 (found). Area a bog with water all over except at fence ridge. Found a small stake (1 1/4" diameter by 12" long) lying flat. Then found 5" diameter post sharened to a good point with one side flattened, also lying flat. Both about 6" deep. Accepted these as stake and post recorded by Fraser but pumped out by bog. Set Cast Iron Cap on telspar pipe as corner at appx location that point of post found and on the line from the E 1/4 18 over the center 18 (this also E-W location assuming W.F. set 1/64 West of center 18 at proper gov't prop). Drove survey marker sign and post 1.1 west corner 1' East of N-S fence and 10 1/2' North of fe. corner complex to fences E-W-N-S. Remains of old post on E side of CIC.

2-4-2010 Olmsted County Survey Crew found CIC/p2 up 0.5' in good condition. Post w/sign gone.

2-22-2010 Olmsted County Survey Crew found CIC/p2 up 0.5' in good condition. Set post w/sign 2' north.