Certificate of Location of Government Corner

ID#: 552006 **Description:** 1/4 SEC COR 19 20 55 **Date Set:** 9/24/1992 **County:** Olmsted

Section: 20 **Township:** 105N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' south of E-W fence.
This corner is located by GPS measurement.

Corner History:

5-1854 Michael Karrick 40.00 set quarter section post in mound with trench, pits, charred stake and Osage Orange seeds NE and SW.

9-1876 Thomas Hunter, County Surveyor (P.304, No.299) found 1/4 post in mound measured South 39.98 chains.

6-21-1895 W. Fraser (P.582 No.531) found mound with stone in center and corner post of fence set by its side. Drove stake, marked 1/4 corner by side of stone (this exact quote) no meas.

9-4-1992 County Surveyor dug around corner post to fences E-W-N many stones in this area. Found old post hole with wood dug int. clay at 2 1/2' deep. Found stone 6" x 8" x 14" in this hole, found another old post hole part way into new coner post with wood. Bottom of post just North of stone, removed stone.

9-24-1992 County Surveyor set cast iron cap on telspar pipe at stone location South of corner post 1' South of E-W fence and inline with fence North. Nailed sign on corner post CSD in corner post North 1.32'

10-12-2010 County survey crew found cast iron cap down 0.2' in good condition.