Certificate of Location of Government Corner

ID#: 552706 **Description:** 1/4 SEC COR 27 28 55 **Date Set:** 6/2/2003 **County:** Olmsted

Section: 27 **Township:** 105N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1 1/2' west of centerline of N-S twp road and 3' south of fence east
This corner is located by GPS reference stations "Silo A & B"

Corner History:

Gov't notes Michael Karrick 40.00 set quarter section post in mound with trench, pits and charred stake and Osage Orange seeds NE and SW. 45.12 road bears NW.

7-1893 W. Fraser (P.523 No.488) could find nothing at this corner so set iron stake as corner M & L 39.99.

7-28-1971 County Surveyor set 40d on transit line in line fences E & W.

8-6-1971 County Surveyor dug entire road 8' N & S found nothing.

8-13-1971 County Surveyor dug again West and found nothing.

9-25-1990 County Surveyor found 120d spike set (1971) in centerline N-S road and line of fence East.

4-28-2003 County Surveyor found 120d spike in good condition.

5-6-2003 County Surveyor found 120d spike in good condition down 0.4'.

6-2-2003 County Surveyor set 4' Telspar pipe w/CIC down 0.5' from computed coordinates from GPS data. Monument falls 1.5' West of centerline of 90th Ave SW and 3.0' South of fence running East.

3-20-2009 County Surveyor found cast iron cap on telspar pipe down 0.3' in good condition.