Certificate of Location of Government Corner

ID#: 601806 **Description:** W 1/4 SEC COR 18 60 **Date Set:** 7/27/2009 **County:** Winona

Section: 18 **Township:** 106N **Range:** 10W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 71' NE of centerline of twp road on curve
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes: North 40.00 chains, set quarter section post in mound with trench and pits and deposited charred stake and hawthorn seeds. Top of dividing ridge north 15 chains.

7-26-1978 WHKS found and used 2" pipe as corner.

6-6-1985 Yaggy Associates shows 2" iron pipe at corner.

7-9-1999 Roger Brand & Associates found and used pipe as corner.

4-11-2000 Olmsted County Surveyor found 2" pipe up 0.2' in good condition.

5-7-2009 Olmsted County Surveyor found 2" pipe at surface bent in good condition.

7-10-2009 Olmsted County Surveyor found 2" pipe leaning up 0.4'. Dug down to where pipe straightened and removed, took local ties to center of hole and set 6' telspar pipe w/CIC down 0.2'. Post w/sign 2' north.

7-27-2009 Olmsted County Surveyor found cast iron cap on telspar pipe up 0.2' in good condition, coordinates did not match when checked w/RTK, removed pipe. Set 7' telspar pipe w/CIC down 0.2' from coordinates.