Certificate of Location of Government Corner

ID#: 601905 **Description:** W SEC COR 19 30 60 **Date Set:** 11/2/2006 **County:** Winona

Section: 19 **Township:** 106N **Range:** 10W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1 1/2' north of E-W fence and in line with Cottonwood row south
Post w/sign 1 1/2' south
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes: N 80.00 chains set post corner. Blk Oak 14" N69°W 296 links, White Oak 8" S60°W 356 links, Burr Oak 10" N48°E 332 links, Burr Oak 16" S14°E 611 links.

6-1857 John Fraser (P.30 No.47 S.24) used corner to set center and 8 1/16 corners. 1/16 north and west of above corner 39.90 north to E 1/4 24 then 39.90 2633.4 N to E 13-24.

1943 county highway department (B.180P) found 4x8 stone 12" up 2' north corner post. Meas south 5267.1 then 5267.1 to Twsp corner. Meas south to old post remains 1' north of fence running east 2631.4 south of north each cor .25 then 2635.7 south to SE cor 25

1-7-1972 County Surveyor ran and meas from E 13-24 1-1/4" pipe, started S on 64' west, line fell 98.5' west of 4"x8" top limestone, down 8" ± which lies north of corner post complex. A 1" iron pipe up 2" lies south of stone about 1.3' ± and lines with fences E and W and line of huge trees south. Meas 5269.16 R John Fraser 6-1857 P.30 No.47 midway 39.90 2633.4

5-9-1972 County Surveyor found 4"x10"x24" limestone at E 1/4 24 4' deep with cross. Meas N to above stone 2634.7 then meas N to E 13-24 2634.46 above 1/4 corner .58' E of direct line .12' N of midway.

6-1984 Tom Ferguson survey in sec 30-106-10

6-7-1984 County Surveyor found 4"x8" top stone down ± 8" 1-1/2' north of E-W fence and in line with row of huge cottonwood trees running south with the first one south dead and fallen over and lying just east of stone. There is a 1" iron pipe ± 1.3' south of the center of the stone (pipe is just about flush with ground or maybe down 2"). Traverse was run SW'ly and south.

12-14-1999 County Surveyor found 4"x8" top stone ± 18" long 1 1/2' north of E-W fence line 3" under ground surface. It falls in line of large Cottonwood row south and 1.3' north of 1" pipe sticking 2" above ground surface. Set survey marker sign and post 1 1/2' south of stone.

11-2-2006 County Surveyor found 4"x8"x20" stone with drill hole and cross down 0.4' in good condition. Removed stone and set 6' telspar pipe w/cast iron cap up 0.1'.