Certificate of Location of Government Corner

ID#: 610106 **Description:** 1/4 SEC COR 1 2 61 **Date Set:** 10/12/1994 **County:** Olmsted

Section: 01 **Township:** 106N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is up 0.7'
The corner falls in line with fences N-S-E-W and between 2 CP
Sign on corner post north 1'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes: Course south 39.96 chains set post at quarter sec corner, made mound, trench and pits.

10-15-1974 Went to corner much fill at corner, found nothing used cor fe post for measuring only.

10-12-1994 County Surveyor dug from 6' east of 3 C.P. fence int west to posts. This is a fence intersect 4 ways that is filtered in with 4' of top soil. Clay at the fence was 4-1/2' deep, we found a 6" diameter post mark running 7" into clay. As I dug down and scraped off clay the mark got narrower. At the bottom there seemed to be a small spot beside it. There were 5 post locations here. The above mark was the only one making it into clay. The next deepest stopped at clay line. The next three were more modern and in a cluster. The rest of the area was clean clay. The hole was 6' E-W and 5-1/2' N-S. Set cast iron cap on telspar pipe 6' long at post mark location. This falls in line of fences 4-ways and between 2 C.P.'s.

8-23-2010 County survey crew found CIC in good condition