Certificate of Location of Government Corner

ID#: 610205 **Description:** SEC COR 2 3 10 11 61 **Date Set:** 7/15/2002 **County:** Olmsted

Section: 02 **Township:** 106N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' north of centerline of E-W twp road and in line with fence south
County Survey Disk in PP #50196 SSE 33.20'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes: Set post at corner, deposited handful of white flint, made mound, trench and pits.

10-4-1983 County Surveyor dug from T.N. set in centerline E-W road and in line fe. south, north 7', south 6', east 4', and west 4' + by 2-1/2' deep to clay. Found where someone had dug 4' diameter and centered 2' west of the T.N. Diggings beneath the 2nd road (nail down 1-1/2'), found nothing further.

6-23-1995 County Surveyor set CIM over 5/8" iron on line between section corner east and west and on line from No. 2-3 over 1/4 cor 2-3. The corner is 1' north of centerline E-W Twp. road and in line of fence south. CSD in PP #50196 SSE 33.20'.

7-10-2000 County Surveyor found CIM lying on its side.

7-15-2002 County Surveyor found broken CIM. Removed CIM and found rerod down 1.1'. Removed rerod and set 6' cast iron cap on telspar pipe.