Certificate of Location of Government Corner

ID#: 610206 **Description:** 1/4 SEC COR 2 3 61 **Date Set:** 10/11/1994 **County:** Olmsted

Section: 02 **Township:** 106N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1 1/2' east of CP to fences E-W-N
Sign on CP 1 1/2' west
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes Course S 9' W, set corner 40.00 chains, then 39.80 to N sec set post at quarter sec corner deposited handful yellow flint, made mound, trench and pits.

10-11-1994 County Surveyor dug from CP location south to 10' to cover the gov't proportion. We dug 5' wide centering on CP. We dug around the CP Eric found 3 pieces of yellow flint which the gov't surveyors stated they deposited hand full of yellow flint down about 1' deep below raised fence row. We found an old post stub north of the flint. The bottom of stub was 3' deep. The newest post and the old post disturbed this area badly, because of the yellow flint and old post being very close together we will set corner at post location which matches fence lines E-W-N. At the gov't proration position it was open pasture land on hill side being clean except for gopher digging. We set cast iron cap on telspar pipe 6' long at the post stub position. This falls 1' east of east edge 8" CP to fence E-W-N. We nailed surveyor sign on corner post.

12-4-2008 County Surveyor found cast iron cap on telspar pipe up 0.5' in good condition.