Certificate of Location of Government Corner

ID#: 610304 **Description:** 1/4 SEC COR 3 10 61 **Date Set:** 6/23/1995 **County:** Olmsted

Section: 03 **Township:** 106N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 13' south of centerline of E-W twp road, 7 1/2' west of fence north and 10' west of fence south
This corner is located by GPS measurement

Corner History:

West on true line between sec 3 & 10. 40.02-1/2 set post at quarter sec corner. Deposited white flint and made mound, trench, and pits. Planted cherry seeds SW and NE 80.05 to sec corner.

8-24-1977 County Surveyor dug out entire surface of E-W road at T.N. set in centerline and in line with fences N&S. Dug 5' E and 5' W of T.N. on S half of the road and wider on the N half. Dug 7' deep to clay over 1' of black dirt on clay. Found nothing, set a 1/2"x2' rod back at T.N. location.

6-23-1995 County Surveyor set cast iron cap on telspar pipe 4' long on south shoulder of E-W twp road midway between section corners E&W. The corner falls 13' south of centerline E-W Twp road and 10' west of fence S and 7-1/2' west of fence N.

7-10-2000 County Surveyor found cast iron cap on telspar pipe in good condition.

3-21-2003 Roger Brand found monument in good condition. He also removed 1/2" x 24" rerod that was set at traverse pt. Location.

7-29-2008 County Surveyor found cast iron cap on telspar pipe down 1' in good condition.